

07-15-05

Cafe

HARNESSES
DICKEY

H. Keith Miller
Direct Dial: 248.641.1206
hkmler@hdp.com

10/624161

IFW



July 14, 2005

Director for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Re: U.S. Patent No. 6,899,207 - Issued May 31, 2005
Patentee: Stefan Deferme et al
Assignee: Tenneco Automotive Operating Company Inc.
Title: Extra Support Area For Valve Disc
Attorney Docket No. 1316N-001680

Sir:

We have noted in proofreading the above referenced United States patent the following errors:

Col. 1, line 45 (Appln. pg. 2, line 12), "dampening" should be --damping--;

Col. 3, line 42 (Appln. pg. 6, line 21), "reserve tube 36" should be --reservoir tube 36--; and

Col. 7, line 5 (Appln. pg. 14, line 14), "are" should be --area--.

Kindly make these errors of record in your file.

Very truly yours,

H. Keith Miller, Esq.
Reg. No. 22,484

HKM/rf

Certificate
AUG 17 2005
of Correction

FOR COURIER DELIVERY ONLY
Harness, Dickey & Pierce, P.L.C.
Attorneys and Counselors
5445 Corporate Drive
Troy, Michigan 48098
248.641.1600

P.O. Box 828
Bloomfield Hills, MI 48303 U.S.A.

CABLE
Patents Troy, Michigan
Telex No. & Reply
287637 Harness UR
Telefacsimile 248.641.0270

Metropolitan
Detroit, MI St. Louis, MO Washington, D.C.

www.hdp.com

EV 570 164 755 US